
	Doc.Type PM550 Release Note	Author SW Team		Page of Pages 1 / 3
	Model PM550	Doc.No. -	Rev. V52	Date Aug 24, 2021

PM550 Release Note

PointMobile Co., Ltd.
S/W R&D Team

COMPANY CONFIDENTIAL
DO NOT MAKE COPIES

	Doc.Type PM550 Release Note	Author SW Team		Page of Pages 2 / 3
	Model PM550	Doc.No. -	Rev. V52	Date Aug 24, 2021


PM550 Android Release Note

1. Revision History

Revision	Update	Description
V01	Apr 27, 2021	55.12/62 (Apr 27 2021) <ul style="list-style-type: none"> - Updated security patches to 2021-04-05. - Fixed Print Demo automatically prints when it connected to a printer. - The scanner aimer may flash on the login screen by the trigger key even if the trigger is disabled. - It keeps the scanner beam is on by triggering scanning on resuming. - Supported press/release decode for EX25.
V02	Aug 24, 2021	55.13/63B1 (Aug 02 2021) <ul style="list-style-type: none"> - Updated security patches to 2021-08-05. - Scan Key Trigger Mode (Single scan mode) <ul style="list-style-type: none"> ✓ Supported press & release decode for SE4750, EX25. - Added trigger enabled status on notification icon. - Added FlagAttack patches of Qualcomm. - Print Demo is failed to print sample to BIXOLON. - Supported new battery serial reading and writing - In scanner, keep single scan mode when it leaves from continuous or auto scan modes. - Fixed that scan beep is muted during continuous scan testing. - Audio parameter is updated to 55.A03. <ul style="list-style-type: none"> ✓ Tuned maximum speaker volume. - Added battery charging animation. - Direct Clone supported to backup and restore enabling battery charging animation.
V03	Aug 24, 2021	55.13/63 (Aug 20 2021) <ul style="list-style-type: none"> - Fixed that Print Demo displays connected toast message on trying to connect. - Fixed it doesn't display audio parameter version. - Added Scan Settings information into devinfo.html. - Fixed Print Demo is crashed during connecting.

2. Known Issues

3. GMS Package

	Doc.Type PM550 Release Note	Author SW Team		Page of Pages 3 / 3
	Model PM550	Doc.No. -	Rev. V52	Date Aug 24, 2021

4. SDK

- 55.13B1
 - ✓ SDK V3.21.1
 - Improved RFID related models.

5. TP Firmware version information

- 55.00B9
 - ✓ Firmware: 55.T.03
 - Improved touch performance on side edge of display

6. Audio parameters

- 55.13B1
 - ✓ 55.A.03

7. Wi-Fi version information

- 55.06B7
 - ✓ Configuration: 55.W.9

8. Scanner API version information

- 55.11
 - ✓ SE4750
 - SDL_010-R00
 - ✓ N6703/6603
 - API revision: 2020.05.858
 - Decoder revision: 2020.3.9984
 - ScanDriver revision: 3.091

9. Android security patch level

- 55.13/63B1
 - ✓ Aug 5, 2021