
	Doc.Type Release Note	Author SW Team		Page of Pages 1 / 3
	Model PM66 Android	Doc.No. -	Rev. V27	Date 10-26-2021

PM66 Android Release Note

Point Mobile Co., Ltd.
S/W R&D Team

COMPANY CONFIDENTIAL
DO NOT MAKE COPIES

	Doc.Type Release Note	Author SW Team		Page of Pages 2 / 3
	Model PM66 Android	Doc.No. -	Rev. V27	Date 10-26-2021

PM66 Android Release Note

1. Revision History

Revision	Date	Description
V01	09/06/2021	76.16 <ul style="list-style-type: none"> - [Touch] Support touch IC which address is 0x4B
V02	10/25/2021	76.17 <ul style="list-style-type: none"> - [Battery] Fixed an issue that it cannot read float voltage on new battery package - Fixed an issue that key down event is reported repeatedly when pressing any key on first reboot

2. Known Issues

- We found the Wi-Fi re-connection fail problem after rebooting for 802.11r in 76.05. There are two recovery methods. One is going to "Settings > WLAN", the other one is doing to suspend and then to resume the device with POWER key.

3. GMS Package


- 76.14
 - ✓ Updated Google Messenger: v2.0.768 → v2.8.040

4. SDK

- 76.15
 - ✓ Unified SDK V3.19.2
 - Added NAND type: SAMSNG KMQE60013B_B318.
 - Supported RFID device.

5. TP Firmware version information

- 76.14
 - ✓ 76.T.13
 - Improved button touch not working problem on low temperature.

	Doc.Type Release Note	Author SW Team		Page of Pages 3 / 3
	Model PM66 Android	Doc.No. -	Rev. V27	Date 10-26-2021

6. Audio parameters

- 76.09C1
 - ✓ 76.A.10
 - Updated audio parameter for CTSV audio speaker test. (#12321)

7. Wi-Fi version information

- 76.12
 - ✓ Configuration : 70.W.13
 - [WLAN] Improved the communicable distance on a specific channel. (#14580)
 - Modified TX power limit for the bonding channel.
 - Modified TX limit value for each regions.
 - Modified RSSI offset for 5G band.

8. Camera tuning version information

- 76.13
 - ✓ Rear: 70.C.IMX258.09

9. N6603 2D Scanner API version information

- 76.14
 - ✓ API Revision: 2020.05.858
 - ✓ Decode Revision : 2020.3.9984
 - ✓ ScanDriver Revision: 3.061

10. Android security patch level

- 76.15
 - ✓ 2020-12-05